Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1822/1

Work Order Type: Weatherization Audit Name: 18018UE-1822

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1822

Alt. Client ID: Carter

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Agency Contact: Hoard, Howard Work Phone: (423) 246-6180

Cell Phone: Email Address:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Home 1956 model has sq. ft. 1160 58' x 20' Client has no wall insulation 2" of attic insulation

and no floor insulation only 580 sq, ft. can be done.

The other half of crawlspace has plywood up.

Has a shingle roof and 2 sliding glass doors and a front solid wood door (need W/S)

sliding glass door at rear of house will not closw and front side french door need caulked and W/S.

Client uses wood as back up.

Questionble wiring and the water heater client hook-up relief pipe on clean out.

Uses protable electric heater.

Client Name:
Client ID: 18018UE-1822
Alt. Client ID: Carter

Work Order (Bid Form)
Work Order Name: WO/18018UE-1822/1

DOE Weatherization Assistant Version 8.6.0

Report Run On: 4/4/2012

Page 1 of 9

Measures

| Comment | ration Redctn | | | Component | ts | | | Inspecte |
|-------------------|---|-------|--------|--------------|-------|-----|------------|----------|
| | | | | Estimated | | | Actual | |
| Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Labor | labro to repair wall | SqFt | 2 | | | | | |
| Miscellaneous Su | Repair hole in wall at base of tub (Bath) | SqFt | 2 | | | | | |
| Miscellaneous Su | Seal under sink in bath and kitchen | Each | 2 | | | | | |
| Labor | spray foam piping | Each | 2 | | | | | |
| Miscellaneous Su | install light cover gasket kitchen | Each | 2 | | | | | |
| Labor | install covers (Light Switch) | Each | 2 | | | | | |
| Construction Mate | install trim to window | l.ft | 9 | | | | | |
| Labor | install trim | Each | 1 | | | | | |
| Miscellaneous Su | install caul to interior windows (10) | Each | 10 | | | | | |
| Labor | caulk windows | Each | 10 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | , | Sub Total: | |

| Measure 2 DWH | I Tank Insulation | | | Componen | its | | | Inspected |
|--------------------|-----------------------|-------|--------|--------------|-------|-----|------------|-----------|
| Comment | | | | | | | | |
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | DHW Tank Insulation | Each | 1 | | | | | |
| 1 Hot Water Equip | DHW Tank Insulation | Each | 1 | | | | | |
| Other Detail | | | | | | , | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] . | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| | Measure 3 Ligh | ting Retrofits | | | Componen | ts LT1,L | T2,LT3 | | Inspected |
|---|------------------|------------------------------|--------------|--------|------------------|----------|--------|------------------|-----------|
| C | Comment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Lighting | Compact Fl 13 Watt (living) | Each Lamp | 2 | | | | | |
| 1 | Labor | Compact FI 13 Watt | Each Lamp | 2 | | | | | |
| 2 | Lighting | Compact FI 13 Watt (kitchen) | Each Lamp | 3 | | | | | |
| 2 | Labor | Compact Fl 13 Watt | Each Lamp | 3 | | | | | |
| 3 | Lighting | Compact FI 13 Watt (Bed) | Each Lamp | 2 | | | | | |
| 3 | Labor | Compact Fl 13 Watt | Each Lamp | 2 | | | | | |
| (| Other Detail | | | | , | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |

| Measure 4 Atti Comment | ic Ins. R-30 | | | Componen | ts A1 | | | Inspected |
|---|---|----------------------|----------------|---------------------|----------|-----|------------------|-----------------|
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | Attic Insulation - Blown Fiberglass - R-30 | SqFt | 1160 | | | | | |
| 1 Insulation | Attic Insulation - Blown Fiberglass - R-30 | SqFt | 1160 | | | | | |
| Other Detail | | | | | | _ | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | | Sub Total: | |
| Measure 5 DW Comment | /H Pipe Insulation | | | | | | | |
| | • | | | Componen | | | | Inspected |
| # Material / Labor | · | Units | | Estimated | 1 | Ofv | Actual | |
| # Material / Labor1 Insulation | Description / Comment DHW Pipe Insulation | <i>Units</i> Each | Qty 1 | - | | Qty | | Inspected Total |
| | Description / Comment | | Qty | Estimated | 1 | Qty | Actual | |
| 1 Insulation | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| 1 Insulation1 Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| 1 Insulation1 Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| 1 Insulation1 Labor | Description / Comment DHW Pipe Insulation | Each Each | Qty 1 1 | Estimated | 1 | | Actual | |
| 1 Insulation1 Labor | Description / Comment DHW Pipe Insulation | Each Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |

| Comment | or Ins. R-19 | | | Componen Estimated | | | Actual | Inspected |
|--|--|----------------------|----------------|---------------------|--------|-----|------------------|-----------|
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 580 | | | | | |
| 1 Labor | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 580 | | | | | |
| Other Detail | | | | | | 1 | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| | | | | | | | | |
| Measure 7 Wa | II Insulation | | | Componen | ts WL1 | | | Inspected |
| Comment | | | | Estimated | | | Actual | |
| Comment # Material / Labor | Description / Comment | Units | Qty | | | Qty | | Inspected |
| Measure 7 Wall Comment # Material / Labor 1 Insulation | | <i>Units</i> SqFt | | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown | | Qty | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 140 | Estimated | | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 140 | Estimated | | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 140 | Estimated | | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt SqFt | Qty 140 | Estimated | | | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt SqFt | Qty 140 | Estimated Unit Cost | | | Actual Unit Cost | |

| Measure 8 Wa Comment | II Insulation | | | Componen | ts WL3 | | | Inspected |
|---|--|----------------------|------------------------|--------------------------------|----------|-----|------------|--------------------|
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 143.1 | | | | | |
| 1 Insulation | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 143.1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| | | | | | | | | |
| | II Insulation | | | Componen Estimated | | | Actual | Inspected |
| Comment | Il Insulation Description / Comment | Units | | Componen Estimated Unit Cost | | Qty | | Inspected |
| Comment # Material / Labor | | <i>Units</i> SqFt | Qty 377.1 | Estimated | 1 | Qty | Actual | Inspected Total |
| Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown | | Qty | Estimated | 1 | Qty | Actual | |
| Comment # Material / Labor 1 Insulation | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 377.1 | Estimated | 1 | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 377.1 | Estimated | 1 | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 377.1 | Estimated | 1 | Qty | Actual | |
| # Material / Labor Insulation Labor | Description / Comment Wall Insulation - Blown Cellulose - 2x4 Filled Wall Insulation - Blown | SqFt | Qty 377.1 377.1 | Estimated | 1 | | Actual | |

| | Measure 10 Wall | Insulation | | | Componen | ts WL4 | | | Inspected |
|--------------------|--|--|----------------------------|----------------|--------------|--------|-----|------------|-----------------|
| C | omment | | | | | | | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 390.3 | | | | | |
| 1 | Labor | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 390.3 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measure | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | | | | | | | |
| | Measure 11 Pres | sure relief piping need | ed | | Componen | ts | | , | Inspected |
| | | sure relief piping need | ed | | - | | | | Inspected |
| C | Measure 11 Pres | | | | Estimated | 1 | Otv | Actual | |
| <i>C</i> | Measure 11 Pres | Sure relief piping needs Description / Comment labor to install pressure relief pipe | ed <i>Units</i> Each | Qty 1 | - | | Qty | | Inspected Total |
| C # 1 | Measure 11 Pres Comment Material / Labor | Description / Comment labor to install pressure | Units | Qty | Estimated | 1 | Qty | Actual | |
| C # 1 | Measure 11 Prescomment Material / Labor Labor | Description / Comment labor to install pressure relief pipe Install pressure relieef | <i>Units</i> Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 | Measure 11 Prescomment Material / Labor Labor Health and Safety | Description / Comment labor to install pressure relief pipe Install pressure relieef | <i>Units</i> Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 | Measure 11 Prescomment Material / Labor Labor Health and Safety | Description / Comment labor to install pressure relief pipe Install pressure relieef | <i>Units</i> Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| # 1 | Measure 11 Prescomment Material / Labor Labor Health and Safety | Description / Comment labor to install pressure relief pipe Install pressure relieef | <i>Units</i> Each | Qty 1 1 | Estimated | 1 | | Actual | |

| Comment | Monitor is Needed | | | Componen | ıts | | | Inspecte |
|--|--------------------------------------|----------------------|----------------|---------------------|-------|-----|------------------|----------|
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | Labor | Each | 1 | | | | | |
| Health and Safety | CO monitor | Each | 1 | | | | | |
| Other Detail | | | | 1 | | 1 | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] | Sub Total: | |
| Field Notes: | | | | | | | | |
| Measure 12 Smo | ke Detector is Needed | | | Componen | its | | | Inspecte |
| Comment | | | | | | | | |
| | | | | Estimated | 1 | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | | | Qty | | Total |
| # Material / Labor | Description / Comment | <i>Units</i> Each | | Estimated | 1 | Qty | Actual | |
| # Material / Labor Health and Safety | Description / Comment | | Qty | Estimated | 1 | Qty | Actual | |
| * Material / Labor Health and Safety Labor | Description / Comment Smoke detector | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| # Material / Labor Health and Safety | Description / Comment Smoke detector | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| Material / LaborHealth and SafetyLabor | Description / Comment Smoke detector | Each | Qty 1 | Estimated | 1 | | Actual Unit Cost | |
| # Material / Labor Health and Safety Labor | Description / Comment Smoke detector | Each | Qty 1 1 | Estimated | 1 | | Actual | |
| # Material / Labor Health and Safety Labor Other Detail Field Notes: | Description / Comment Smoke detector | Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| # Material / Labor Health and Safety Labor Other Detail | Description / Comment Smoke detector | Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| # Material / Labor Health and Safety Labor Other Detail | Description / Comment Smoke detector | Each | Qty 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |